




## ELECTRICAL SYSTEM (CONTINUED)

### WIRING DIAGRAM (For a larger version of the below diagram please visit badboymowers.com and click the parts manuals section)

Fig. 25



PCA		PRECISION CABLE ASSEMBLYS		PCA		PRECISION CABLE ASSEMBLYS		PCA		PRECISION CABLE ASSEMBLYS	
REV		DATE		REV		DATE		REV		DATE	
A		FIRST CREATED		SL		02/02/18		CX		02/02/18	
B		UPDATED		SL		02/24/18		CX		02/24/18	
C		ADD T10/T11		SL		07/12/18		CX		07/12/18	
D		Delete P8/P9/P2		SL		10/12/18		CX		10/12/18	
E		REMOVE T10/T11		SL		10/24/18		CX		10/24/18	