




ELECTRICAL SYSTEM (CONTINUED)

WIRING DIAGRAM (For a larger version of the below diagram please visit badboymowers.com and click the parts manuals section)

Fig. 23



PCA		PRECISION CABLE ASSEMBLIES		PCA		PRECISION CABLE ASSEMBLIES	
A		FIRST CREATED		SL		02/02/18	
B		UPDATED		SL		02/24/18	
C		ADD T10/T11		SL		07/12/18	
D		Delete P8/P9/P2		SL		10/12/18	
E		REMOVE T10/T11		SL		10/24/18	