




BAD BOY MOWERS

ELECTRICAL SYSTEM (CONTINUED)

WIRING DIAGRAM (For a larger version of the below diagram please visit badboymowers.com and click the parts manuals section)

Fig. 24



PCA									
FUSION CABLE ASSEMBLIES									
REV	DATE	BY	CHK	APP	REV	DATE	BY	CHK	APP
1	11/08/09	MS							
TITLE: WIRING SCHEMATIC									
DRAWN BY: JNO BOY									
CHECKED BY: JNO BOY									
DATE: 11/08/09									
SCALE: 1:1									
APPROVALS: JNO BOY									